To: Allen.Sorenson@state.co.us[Allen.Sorenson@state.co.us]

From: Way, Steven

**Sent:** Fri 2/27/2015 5:15:45 PM

Subject: FW: Gold King Revised Approach

removed.txt

Gold King Mine.docx

Allen, here's the revised plan.

Steve

Steven Way

Federal On-Scene Coordinator

**Emergency Response Unit** 

US EPA - Region 8

1595 Wynkoop Street

Denver, CO 80202

Office: 303-312-6723

From: Matt Francis [mailto:m.francis@erllc.com]

**Sent:** Friday, February 27, 2015 10:02 AM

To: Way, Steven

Subject: FW: Gold King Revised Approach

From: Bob Heeter [mailto:bheeter@harwest.com]
Sent: Thursday, February 26, 2015 11:52 AM

To: Matt Francis

Subject: Gold King Revised Approach

Matt, does this look better?

Thank you,

**Bob Heeter** 

Superintendent



HARRISON WESTERN CONSTRUCTION CORPORATION

1208 Quail Street

Lakewood, Colorado 80215

T (303) 234.0273 x202 | C (775-340-1776)

F (303) 237.9868 | www.harrisonwestern.com